

Fig. 4. Simple Fixture for Holding Three Sixes of Steql FlAng^s, while boring, facing, and cutting Packing Groove:;

The screws N are set into the ring from the rear and are located in different places for the various rings. The fixture has three T-slots G in order that the damps E may be conveniently adjustable by means of the T-bolts F which enter